

Access Compliance Report Public Rights-of-Way (Curb Ramps)

Intersection ID: 14132	Main Street: LEXINGTON_AV	Cross Street: MT_VERNON_AV	Location: NW
ADA ID: 4948773F5217	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No Severity Score: 7.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.
Remove & Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

**Not Found, R304.5.2, R305.1.4,
R305.2, R302.7, R304.5.4**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	77.0	No	Grade Break?	No
Yes	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	4.8
Yes	Ramp Slope (%)	5.1	N/A	Grade Break XSlope (%)	3.0
Yes	Ramp XSlope (%)	1.6			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	59.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	1.5	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	20.5
N/A	Shared Landing?	Yes	No	DWS Offset RT (in)	5.0
No	Gutter Ponding?	Yes	No	Gutter Slope (%)	22.2
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.1
N/A	Painted X Walk1?	No		Road Slope (%)	4.6
	X Walk 1 Direction	To S		Road X Slope (%)	0.9
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.9	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	9.7

Total Cost: \$ 2350.00

