cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 4672 Main Street: W_MALLARD_CREEK_CHURCKrRSs Street: SENATOR_ROYALL_DR								Location:	NE
ADA ID: 49F765C72500					Initial Pass/Fail: Fail Overall Compliance: No				
Codes/Mitigation Info/Possible Solution				Initial Pass/Fail: Fail Overall Compliance: No Seve Field Measurements/Component Complian					10.70
Possible Solutions:				Compliance Description Data Compliance Description Data					
	A A A A A A A A A A A A A A A A A A A			N/A	Ramp Length (in)	131.5	No	Ramp Slope (%)	<u>10.1</u>
		Remove & Replace Entire Ra	amp.	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	4.5
Process Har Mary	YE AND TO			N/A	Flare Type LT		N/A	Flare Type RT	4.5 N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 4/5	1		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	The second second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
e s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	L. C.	N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	- Harrison			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
W MALL	ARD GREEK GUIDAN D	1. 1.		N/A	Shared Landing?	N/A		DWG Oliset (III)	11/2
	ARD CREEK CHURCH RI	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Par m			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
E	2 / / an	R304.2.2		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A N/A
	t.			N/A	X Walk 1 Direction	To NW	N/A	X Walk 2 Direction	N/A
	A Merine -	ă de la constante de		N/A		120.0	N/A		N/A N/A
Ctra et 1 Name				N/A	X Walk 1 Width (in)		N/A	X Walk 2 Width (in)	
Street 1 Name	SENATOR ROYALL DR				X Walk 1 Slope (%)	9.6		X Walk 2 Slope (%)	N/A N/A
Stop Condition-Street 2	Signal			N1/A	X Walk 1 X Slope (%)	5.5 Xaa	N/A	X Walk 2 X Slope (%)	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		T.1.1.0		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3400.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

