

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10019910Main Street: ARDREY\_CREST\_DRCross Street: N/ALocation: WADA ID: 4A0D45AAA421Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 22.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name ARDREY CREST DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

ossible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
•	N
	N
	N
	N
	N
urveyor Notes:	N
N/A	N
	N
	N
	N
ROW/ADA:	N
Not Found, R304.5.1, R304.2.2,	N
R304.5.3	N
	N

	CITY I			
	1			
Mr. San			1 4	

Total Cost:



1850.00

Compl	iance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	9.9
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good

