

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46756Main Street: TAHOE_DRCross Street: PONTCHATRAIN_AVLocation: NWADA ID: 4A2C5FB463C9Ramp Type: PerpInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



Street 1 Name PONTCHATRAIN AV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

COCIDIO COIGNICII					
Possible Solutions:					
Remove & Replace Entire Ramp.					
Cumyayar Nataa					
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.5.1, R304.5.3					
Not i Guila, 1304.3.1, 1304.3.3					

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	oliance Description	Data	
N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.5	
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.7	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
	7.4					





