

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2937Main Street: RIDGE_RDCross Street: STREET_AVLocation:NADA ID: 4A33BC36A0B5Ramp Type: PerpInitial Pass/Fail: PassOverall Compliance: NoSeverity Score:0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
STREET AV
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

1 CCCIDIC CCIALICIT	
Possible Solutions:	Co
Remove & Replace Landing.	N/A
	Ye
	N/A
	N/A
	N/A
	Ye
Surveyor Notes:	Ye
N/A	No
	Ye
	N/A
	N/A
PROW/ADA:	Ye
R304.2.2-Perp, R304.3.2-Para	Ye
• /	N/A
	N/.
	N/A





Total Cost:



500.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.1		
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.5		
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	9.1	Yes	Flare Slope RT (%)	7.3		
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes		
Yes	Landing Length (in)	58.0	Yes	DWS Provided?	Yes		
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes		
No	Landing Slope (%)	2.4	Yes	DWS Length (in)	24.5		
Yes	Landing X Slope (%)	1.9	Yes	DWS Full Width?	Yes		
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0		
N/A	Shared Landing?	No					
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.2		
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	Yes		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		