


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27658Main Street: GUNPOWDER_POINT_DRCross Street: W_S_LEE_CTLocation:NEADA ID: 4A8211F690CFRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	GUNPOWDER POINT ER
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Not Found, R304.2.2

Total Cost: \$ 1850.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	8.7	
	Yes	Ramp Width (in)	53.0	Yes	Ramp XSlope (%)	1.2	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
		X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	N/A	N/A	Clear Space?	N/A	
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Obstruction Type			Storm Grate/Utility Type		
			N/A			N/A	
				Yes	Surface Condition? (G/P)	Good	
10	W.						





