

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13767	Main Street: E_5TH_ST	Cross Street: PARK_DR	Location: W
ADA ID: 4A8CBA923F39	Ramp Type: BlendTrans2	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Detectable Warning System. Restripe Crosswalk(s) To Provide Clear space. Grind Gutter Lip.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305.1.4, R305.2, R302.7, R302.7.2

Total Cost: \$ 1500.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	66.0	Yes	BlendTrans Slope (%)	4.4
Yes	Ramp Width (in)	140.0	Yes	BlendTrans XSlope (%)	0.3
N/A	Flare Type LT	None	N/A	Flare Type RT	None
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	8.0
N/A	Shared Landing?	No			
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	4.8
No	Gutter Lip Ht (in)	0.5	Yes	Gutter X Slope (%)	0.7
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
	X Walk 1 Width (in)	112.0		X Walk 2 Width (in)	111.0
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	2.0
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	4.8
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	2.0		Clear Space?	Yes
	Road X Slope (%)	3.3	No	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Yes	Curb Slope (%)	0.8

Street 1 Name	TRAVIS AV
Stop Condition-Street 1	StopSign
Street 2 Name	PARK DR
Stop Condition-Street 2	StopSign

