

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

48.0

5.4

3.0

5.5

1.7

N/A

N/A

Good

6.6

Intersection ID: 20234Main Street:SHOPTON\_RD\_WESTCross Street:WITHERS\_RDLocation:NWADA ID: 4A9BE272E2ECRamp Type:Combination1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:35

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

Yes

N/A

No N/A

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

Yes

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Type RT

Ramp XSlope RT (%)

Data

48.0

48.0

12.6

1.4

52.0

45.5

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
WITHERS RD
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
PROM/ARA						
PROW/ADA:						
Not Found, R304.5.1, R304.3.2, R304.5.3						
11004.0.0						



Total Cost:



1800.00

N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
	4 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8			Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
					N/A

Yes

Surface Condition? (G/P)

Curb Slope (%)