

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.9

1.0

N/A

Good

Intersection ID: 47457 Main Street: STEELE_CREEK_RD Cross Street: WINGED_TEAL_RD Location: NE

ADA ID: 4B15B50DBBFE Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name

Stop Condition-Street 2

StopSign

Street 2 Name

N/A

Stop Condition-Street 1

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

PROW/ADA: N/A
Not Found, R304.2.2 N/A
N/A
N/A

N/A

Total Cost: \$ 1850.00

No Ramp Slope (%) N/A Ramp Length (in) 52.0 Yes Ramp XSlope (%) Yes Ramp Width (in) 48.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A DWS Provided? Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SE X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 0.2 X Walk 2 Slope (%) X Walk 1 X Slope (%) 9.6 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) N/A N/A Clear Space? N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type N/A

Yes

Surface Condition? (G/P)





