

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.8

6.2

N/A

Good

Intersection ID: 31853 Main Street: TIBBLE CREEK WY Cross Street: WATERLEAF LN Location: Ν **Overall Compliance: No** 25 ADA ID: 4B3D0E417CFF Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

47.0

48.0

N/A

Flare Traversable LT?



Possible Solutions:	Compliance Description
Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A	N/A Ramp Length (in)
	Yes Ramp Width (in)
	N/A Flare Type LT
Remove & Replace Entire Ramp. Surveyor Notes:	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.2.2, R304.5.3	N/A Gutter Lip Ht (in)
	N/A Painted X Walk1?
	X Walk 1 Direction
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%
	X Walk 1 X Slope (
	N/A Ramp inside XWall
	5 101 (21)



