

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A 6.9 5.8

N/A N/A

N/A N/A N/A

N/A

N/A N/A

N/A

N/A

No

To E

N/A

1.9

3.7

N/A

N/A

N/A

N/A

N/A

N/A

N/A

1.9

Good

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Intersection ID: 15303 Main Street: IDEAL WY **Cross Street: MCDONALD AV** Location: NW Ramp Type: Combination2Diag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: 4B74C32D2043

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign **IDEAL WY** StopSign **MCDONALD AV** Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.3

Total Cost:

Compliance Description		Data	Compl	iance	Description
N/A	Ramp Length LT (in)	N/A	N/A	Ram	Length RT (in)
N/A	Ramp Width LT (in)	N/A	N/A	Ram	o Width RT (in)
N/A	Ramp Slope LT (%)	N/A	N/A	Ram	o Slope RT (%)
N/A	Ramp XSlope LT (%)	N/A	N/A	Ram	xSlope RT (%)
N/A	Ramp Length (in)	74.0	Yes	Ramp	Slope (%)
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)
N/A	Flare Type LT	N/A	N/A	Flare	Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?
	X Walk 1 Direction	To S		X Wa	lk 2 Direction
	X Walk 1 Width (in)	N/A		X Wa	lk 2 Width (in)
	X Walk 1 Slope (%)	1.9		X Wa	lk 2 Slope (%)
	X Walk 1 X Slope (%)	0.9		X Wa	lk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?

1.6

0.5 N/A

N/A

N/A

Yes







Road Slope (%)

3200.00