

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25770 Main Street: PINEVILLE-MATTHEWS_RD Cross Street: MCMAHAN_DR Location: SE

ADA ID: 4B7B86874614 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name PINEVILLE-MATTHEWS RD
Stop Condition-Street 2 None
Street 2 Name MCMAHAN DR
Stop Condition-Street 1 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

Not Found, R304.2.2

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 76.0 Ramp Slope (%) 10.1 Yes Ramp XSlope (%) Yes Ramp Width (in) 48.0 1.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To N X Walk 2 Direction To W N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 2.0 X Walk 2 Slope (%) 1.4 X Walk 1 X Slope (%) 2.4 X Walk 2 X Slope (%) 3.2 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.4 N/A Clear Space? N/A N/A Road X Slope (%) 1.5 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)

Good





