

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18716 Main Street: COLONY RD Cross Street: RUNNYMEDE_LN Location: ADA ID: 4B7FD6F2B670 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Signal

Signal

Possible Solutions:

Field Measurements/Component Compliance



RUNNYMEDE LN Street 1 Name Stop Condition-Street 2 Street 2 Name **COLONY RD** Stop Condition-Street 1

Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes: N/A	
PROW/ADA: R304.2.2, R304.5.3	
Total Cost:	\$ 3200.00

Comp	liance Description	Data		pliance Description	Data
N/A	Ramp Length (in)	79.0	No	Ramp Slope (%)	10.3
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.9
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	121.0	N/A	X Walk 2 Width (in)	114.0
	X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	3.5
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	4.0
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
	Road Slope (%)	2.7	N/A	Clear Space?	N/A
	Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





