

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

15.0

0.2

N/A

Main Street: THREE RIVERS CT Intersection ID: 47665 **Cross Street: WRIGLEY DR** Location: W Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 4B82EAE05E68** Ramp Type: Perp Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

<u>Data</u>

48.0

47.0

N/A

No

N/A

3.8

0.8

N/A

To NE



WRIGLEY DR Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No N/A N/A N/A N/A Surveyor Notes: N/A N/A N/A N/A PROW/ADA: R304.5.1, R304.2.2

N/A N/A N/A N/A N/A N/A N/A N/A 1850.00

Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A Total Cost: **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Flare Traversable LT?

Flare Type LT



