

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11986	Main Street: AMITY_CT			Cross Street: N_SHARON_AMITY_RD				Location:	S
ADA ID: 4BC4066CB673 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ran	np.	N/A	Ramp Length (in)	59.5	Yes	Ramp Slope (%)	7.2
			•	No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	3.3
* 1 / Ax				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N	*		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	NY Y			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	The way			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
State of the state		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Service States and Sta	B SAL	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
SH / / /	69) C			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
11130				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The second			N/A	Shared Landing?	N/A			
	and the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
///	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Not Found, R304.5.1, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
All and the second seco			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	AMITY CT				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

