


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11446	Main Street: GRACE_ST	Cross Street: PEGRAM_ST	Location: NW
ADA ID: 4BC53C9462CA	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 17.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	90.0
			Yes	Ramp Width (in)	54.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	0.4
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	60.0
			Yes	Landing Width (in)	58.0
			Yes	Landing Slope (%)	1.3
			No	Landing X Slope (%)	3.4
			N/A	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			No	Gutter Ponding?	Yes
			No	Gutter Lip Ht (in)	2.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	4.1
				X Walk 1 X Slope (%)	2.4
			N/A	Ramp inside XWalk1?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3, R305.1.4, R305.2, R302.7, R302.7.2</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	2.3
			N/A	Flare Traversable RT?	No
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	24.0
			No	DWS Full Width?	No
			No	DWS Offset (in)	5.5
			Yes	Gutter Slope (%)	1.5
			Yes	Gutter X Slope (%)	0.1
			N/A	Painted X Walk2?	No
				X Walk 2 Direction	To E
			N/A	X Walk 2 Width (in)	N/A
				X Walk 2 Slope (%)	2.8
				X Walk 2 X Slope (%)	1.9
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	Yes
			N/A	Clear Space to XWalk (in)	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

