

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44333 Main Street: BROWNE_RD Cross Street: RETRIEVER_WY Location: SE

ADA ID: 4BF9B72ABB84 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



The state of the s	A STATE OF THE PARTY OF THE PAR
Street 1 Name	BROWNE RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Ston Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost: \$ 1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	60.0	Yes	Ramp	Slope (%)	7.4
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)		7.6
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A
	X Walk 1 Direction	To W		X Wal	k 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.4		X Wal	k 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.6		X Wal	k 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfac	ce Condition? (G/P)	Good





