

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30450	Main Street: STEELE_CREEK_RD			Cross Street: SMOKE_MONT_DR				Location:	NW
ADA ID: 4C63DB90583F	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:								liance Description	Data
		Remove & Replace Entire Rar	~~	<u>00111</u>	Ramp Length (in)	54.0		Ramp Slope (%)	11.1
		Remove & Replace Entire Rai	np.	Yes	Ramp Width (in)	48.0		Ramp XSlope (%)	0.8
	A A			N/A	Flare Type LT	-10.0 N/A		Flare Type RT	N/A
	1 m			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
and the second sec	TTANK			N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A		DWS Contrast?	N/A
STICKE MONT OR		,		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
SMORA II		N/A		N/A	Landing X Slope (%)	N/A		DWS Full Width?	N/A
ME MONT INS		2		N/A N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A N/A
The second secon	all the			N/A	Shared Landing?	N/A	N/A	DWS Oliset (III)	IN/A
a T				N/A	0	N/A N/A	N/A		N1/A
		PROW/ADA:			Gutter Ponding?			Gutter Slope (%)	N/A
	1-2012	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	A. 6 4			N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
	a Ver				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name STEELE C	CREEK RD				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

