


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A		Main Street: OAK_DR		Cross Street: MARGARET_WALLACE_RD		Location: NW									
ADA ID: 4CB6A432C00D		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 13.75							
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance											
		Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
		Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		60.0		N/A		Grade Break?		N/A	
				Yes		Ramp Width (in)		60.0		N/A		Grade Break Slope (%)		0.0	
				No		Ramp Slope (%)		10.6		N/A		Grade Break XSlope (%)		0.0	
				No		Ramp XSlope (%)		3.6							
				N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A	
				N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		0.0	
				N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A	
				N/A		Landing Length (in)		0.0		N/A		DWS Provided?		N/A	
				N/A		Landing Width (in)		0.0		N/A		DWS Contrast?		N/A	
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>				N/A		Landing Slope (%)		0.0		N/A		DWS Length (in)		N/A	
				N/A		Landing X Slope (%)		0.0		N/A		DWS Full Width?		N/A	
				N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset LT (in)		N/A	
				N/A		Shared Landing?		N/A		N/A		DWS Offset RT (in)		N/A	
				N/A		Gutter Ponding?		0.0		N/A		Gutter Slope (%)		N/A	
				N/A		Gutter Lip Ht (in)		0.0		N/A		Gutter X Slope (%)		N/A	
				N/A		Painted X Walk1?		No				Road Slope (%)		2.7	
						X Walk 1 Direction		To S				Road X Slope (%)		1.2	
						X Walk 1 Width (in)		N/A				Clear Space?		N/A	
						X Walk 1 Slope (%)		2.7		N/A		Clear Space to XWalk (in)		N/A	
						X Walk 1 X Slope (%)		1.2		N/A		Storm Grate/Utility Hazard?		N/A	
				N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type			
				N/A		Any Obstructions?		N/A						N/A	
						Obstruction Type				Yes		Surface Condition? (G/P)		Good	
										N/A		N/A		Curb Slope (%)	
		Total Cost:		\$		1600.00									

