

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 8442 Main Street: BROOKSHIRE\_BV Cross Street: HONEYWOOD\_AV Location: NW **Overall Compliance: No Severity Score:** ADA ID: 4CC327FA44F0 Ramp Type: Perp Initial Pass/Fail: Fail 1.25

**Codes/Mitigation Info/Possible Solution** 



**HONEYWOOD AV** Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

| · cccibic cciation            |          |  |  |
|-------------------------------|----------|--|--|
| Possible Solutions:           | <u>c</u> |  |  |
| Remove & Replace Entire Ramp. |          |  |  |
| •                             | Y        |  |  |
|                               | N.       |  |  |
|                               | N        |  |  |
|                               | N        |  |  |
|                               | N        |  |  |
| Surveyor Notes:               | N        |  |  |
| N/A                           | N        |  |  |
|                               | N        |  |  |
|                               | N        |  |  |
|                               | N        |  |  |
| PROW/ADA:                     | N        |  |  |
| Not Found, R304.5.3           | N.       |  |  |
|                               | N        |  |  |
|                               | N        |  |  |
|                               | N        |  |  |

Total Cost: 1850.00

| Field Measurements/Component Compliance |                       |       |      |                             |      |  |  |
|---|-----------------------|-------|------|-----------------------------|------|--|--|
| Compliance Description                  |                       | Data  | Comp | liance Description          | Data |  |  |
| N/A                                     | Ramp Length (in)      | 72.0  | Yes  | Ramp Slope (%)              | 7.8  |  |  |
| Yes                                     | Ramp Width (in)       | 48.0  | No   | Ramp XSlope (%)             | 3.0  |  |  |
| N/A                                     | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A  |  |  |
| N/A                                     | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A  |  |  |
| N/A                                     | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A  |  |  |
| N/A                                     | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A  |  |  |
| N/A                                     | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A  |  |  |
| N/A                                     | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A  |  |  |
| N/A                                     | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A  |  |  |
| N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A  |  |  |
| N/A                                     | Shared Landing?       | N/A   |      |                             |      |  |  |
| N/A                                     | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A  |  |  |
| N/A                                     | Gutter Lip Ht (in)    | N/A   | N/A  | Gutter X Slope (%)          | N/A  |  |  |
| N/A                                     | Painted X Walk1?      | No    | N/A  | Painted X Walk2?            | N/A  |  |  |
|   | X Walk 1 Direction    | To SE |      | X Walk 2 Direction          | N/A  |  |  |
| N/A                                     | X Walk 1 Width (in)   | N/A   | N/A  | X Walk 2 Width (in)         | N/A  |  |  |
|   | X Walk 1 Slope (%)    | 1.8   |      | X Walk 2 Slope (%)          | N/A  |  |  |
|   | X Walk 1 X Slope (%)  | 0.6   |      | X Walk 2 X Slope (%)        | N/A  |  |  |
| N/A                                     | Ramp inside XWalk1?   | N/A   | N/A  | Ramp inside XWalk2?         | N/A  |  |  |
|   | Road Slope (%)        | N/A   | N/A  | Clear Space?                | N/A  |  |  |
|   | Road X Slope (%)      | N/A   | N/A  | Clear Space to XWalk (in)   | N/A  |  |  |
| N/A                                     | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A  |  |  |
|   | Obstruction Type      |       |      | Storm Grate/Utility Type    |      |  |  |
|   |                       | N/A   |      |                             | N/A  |  |  |
|   |                       |       | Yes  | Surface Condition? (G/P)    | Good |  |  |
| → Negri                                 | NORTH 1 #             |       |      |                             |      |  |  |





