

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52127	Main Street: VALLEYDALE_RD			Cross	Cross Street: FRED_D_ALEXANDER_BV				Location:	Ν
ADA ID: 4CCDD8BBB453	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	12.5
Co	odes/Mitigation Info/	Field Measure	Field Measurements/Component Compliance							
Possible Solutions:					Compliance Description Data			Compliance Description Dat		Data
A CONTRACTOR OF SAL	Contraction of the	Remove & Replace Entir	re Ram	<b>пр.</b>	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	57.0
A Start Start				•	Yes	Ramp Width LT (in)	55.0	Yes	Ramp Width RT (in)	56.0
A 14 . 3. 14 14 14 14	Stor S				No	Ramp Slope LT (%)	8.5	No	Ramp Slope RT (%)	8.5
The second and the	a with				Yes	Ramp XSlope LT (%)	0.6	Yes	Ramp XSlope RT (%)	1.4
1 1 1 1 1 1 1 1	A NOT				N/A	Ramp Length (in)	56.0	Yes	Ramp Slope (%)	1.5
A TRANSFER	A CONTRACTOR				Yes	Ramp Width (in)	57.0	Yes	Ramp XSlope (%)	0.3
	A A A A A A A A A A A A A A A A A A A	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
by the	5. 5. 5. C	RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A	2				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ALL					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second second					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6 .	A B	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	No.K.	Not Found, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
CONT AN					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	6 6				N/A	Shared Landing?	N/A			
De Martin Plan					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	VALLEYDALE RD				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To SW	1	X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	108.0	1	X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.4	1	X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A	1	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
						N/A	Any Obstruction?	N/A		
Contraction and									Obstruction Type	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	6.5

N/A





