

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4344Main Street:MALLARD\_GROVE\_RDCross Street:POCHARD\_CTLocation:SWADA ID: 4CF6FCF73930Ramp Type:BlendTrans1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name
POCHARD CT
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

R304.5.1, R304.5.3

Total Cost:





3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Comp	liance Description	Data
	N/A	Ramp Length (in)	62.0	Yes	BlendTrans Slope (%)	2.1
	No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	3.1
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To N		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	1.0		Clear Space?	N/A
		Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
	3			N/A	Curb Slope (%)	2.8