

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.6

2.0

N/A

3.6

Yes

Yes

Yes

24.0

Yes

1.0

1.7

1.6

No

To E

N/A

2.2

1.0

N/A

Yes

N/A

No

N/A

Good

Intersection ID: N/A Main Street: LITTLE ROCK RD Cross Street: N/A Location: NW Initial Pass/Fail: Pass **Overall Compliance: Yes Severity Score:** ADA ID: 4D4526E16AB0 Ramp Type: PerpDiag 0

Codes/Mitigation Info/Possible Solution

N/A

N/A

N/A

Total Cost:

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

N/A

Yes

Yes

Yes

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Surface Condition? (G/P)

Flare Traversable RT?

Data

25.0

48.0

5.2

Yes

64.0

48.0

0.9

1.5

No

No

No

0.0

No

To S

N/A

0.1

1.0

Sloped



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

ENTRANCE StopSign LITTLE ROCK RD None Compliance Description N/A Yes N/A N/A N/A Yes Yes Yes Yes N/A N/A Yes Yes N/A N/A N/A

X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) Yes Any Obstructions?

Obstruction Type

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

Flare Traversable LT?

Flare Type LT

N/A N/A Ramp inside XWalk2? 2.1 N/A Clear Space? N/A 1.7 Clear Space to XWalk (in) No Yes Storm Grate/Utility Hazard? Storm Grate/Utility Type N/A

Yes







0.00