

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52612Main Street: GRAHAM_RIDGE_DRCross Street: ALEXANDER_VILLAGE_MAIN_DRLocation:NEADA ID: 4D5AE77885A6Ramp Type: PerpInitial Pass/Fail: Pass Overall Compliance: NoSeverity Score: 10

Codes/Mitigation Info/Possible Solution



Street 1 Name	ALEXANDER VILLAGE MAIN DR
Stop Condition-Street	2 None
Street 2 Name	N/A
Stop Condition-Street	1 N/A

Possible Solutions:
Remove & Replace Entire Ramp. Remove & Replace Gutter.
Surveyor Notes:
N/A
PROW/ADA:
R304.2.1, R304.2.2-Perp, R304.3.2- Para, R304.5.3, R305.2

Total Cost:		\$ 2600.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	6.9		
Yes	Ramp Width (in)	69.0	Yes	Ramp XSlope (%)	0.4		
Yes Flare Type LCurbed_NoWalkSurface		Yes	Flare Type RT	N/A			
Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No		
No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes		
No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes		
No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0		
No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes		
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.0		
N/A	Shared Landing?	No					
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.6		
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.4		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	Yes		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
THE RESERVE	200						





