## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47972	972 Main Street: ALHAMBRA_LN Cross Street: SOUTH_CREEK_RD							Location:	SE
ADA ID: 4D8299FB1B57		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				
· · · · ·			miniari						21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance   Compliance Description Data					
The State State		Possible Solutions:				Data	1	Data	
TRA		Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.0
				No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	5.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ma a subt of				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Solution I have				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
COUNT GREEK				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	TOTOL			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Peterson and Sand			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
A DAUSANCE				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	SOUTH CREEK RD	-			X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	5.9
Street 2 Name	ALHAMBRA LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.2	N/A	Clear Space?	N/A
					Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.0 N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	17/4	Obstruction Type	11/4		Storm Grate/Utility Type	17/74
			3200.00		Obstruction Type	NI/A		Storm Grate/Otimity Type	N/A
						N/A			N/A

Yes Surface Condition? (G/P)

Good

