## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: MEGWOOD_DR Cross Street: ENDHAVEN_LN						Location:	SE	
ADA ID: 4E21023B00F4 Ramp Type: PerpDiag		Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Dat			a Compliance Description		Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.9
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ENDWAVEN LN			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
K K	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ENDHAVEN I	 N			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2 No	10			X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	0.0
Street 2 Name MEGWOOD D	R		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSig	jn			Road Slope (%)	1.9	N/A	Clear Space?	N/A
				Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

es Surface Condition? (G/P)

Good

