cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16286 Main Street: REDDMAN RD				Cross Street: ROCK HOLLOW DR				Location:	NE
ADA ID: 4E4D4BC5EDFF Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Frank States 1	ROCK FOLLOW DR	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp	Nith	N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	8.9
the grant of		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
A- 1997				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	6. 1 6 1 1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Start In	Contraction of the second			N/A	Shared Landing?	N/A			
	The states	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
S. Million Ph	- 3 A - 70	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Contraction of the				X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REDDMAN RD				X Walk 1 Slope (%)	6.1		X Walk 2 Slope (%)	3.6
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	4.2
Street 2 Name	ROCK HOLLOW DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.9	N/A	Clear Space?	N/A
					Road X Slope (%)	6.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

