

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

Good

2.7

Intersection ID: 22467 Main Street: CARMEL RD **Cross Street: TOTTENHAM RD** Location: S **Overall Compliance: No Severity Score:** ADA ID: 4E774D915B8B Ramp Type: Directional1 Initial Pass/Fail: Fail 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Compliance Description

Grade Break?

Surface Condition? (G/P)

Curb Slope (%)

Data

84.0

Ramp Length (in)

Obstruction Type



TOTTENHAM RD Street 1 Name Stop Condition-Street 1 StopSign N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. Yes No No N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A N/A N/A



Total Cost:



1600.00



59.0 N/A Ramp Width (in) Grade Break Slope (%) 0.0 N/A Ramp Slope (%) 11.6 Grade Break XSlope (%) 0.0 Ramp XSlope (%) 8.3 Flare Type LT N/A N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Flare Traversable LT? N/A N/A Flare Traversable RT? N/A 0.0 N/A **DWS Provided?** Landing Length (in) N/A **DWS Contrast?** Landing Width (in) 0.0 N/A N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A Painted X Walk1? No Road Slope (%) 2.5 X Walk 1 Direction To N Road X Slope (%) 2.0 X Walk 1 Width (in) N/A Clear Space? N/A X Walk 1 Slope (%) 2.5 N/A N/A Clear Space to XWalk (in) X Walk 1 X Slope (%) 2.0 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A N/A Any Obstructions? N/A

Yes

N/A N/A