cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



				Stro of -		Loootion	E		
Intersection ID: 31725	Main Street: MOSSYCUP_DR		Cross	Cross Street: GOLDENWILLOW_DR				Location:	E
ADA ID: 4E8786C4EA36	A36 Ramp Type: PerpDiag		Initial P	Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	R	Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	46.5	Yes	Ramp Slope (%)	6.1
		Two New Directional Ramps or		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	4.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
No No 21	1 The			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	19			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E CONTRACTOR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
La contraction of the second s				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
		,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name M	IOSSYCUP DR	-			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	0.4
Street 2 Name GOLDE				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.2	N/A	Clear Space?	N/A
					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

