

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48587 Main	Main Street: STONEY_CREEK_LN		treet:	UNIVERSITY_CITY_B	Location:	NW		
ADA ID: 4E8EA67A333A Ram	3A Ramp Type: BlendTrans1		Initial Pass/Fail: Fail Overall Compliance: N			nce: No	o Severity Score:	10
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:			Compliance Description		Data Compliance Description			Data
LINVERSITY CITY_EV 6. 6. 6. 6	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	94.0	Yes	BlendTrans Slope (%)	4.1
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	2.5
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Ŧ		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	<u> </u>		N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To S		X Walk 2 Direction	To E
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name UNVERSITY CITY E	SV .			X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	0.1
Stop Condition-Street 1 No	10			X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	2.7
Street 2 Name STONEY CREEK I	N		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 StopSi	in			Road Slope (%)	1.7		Clear Space?	N/A
	-			Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

26.8