


Intersection ID: 14283		Main Street: AROSA_AV		Cross Street: DILWORTH_RD		Location:		NE			
ADA ID: 4EA29C3B9010		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		48.0	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		72.0	
						Yes		Ramp Slope (%)		5.2	
PROW/ADA:				R304.5.3		No		Ramp XSlope (%)		2.9	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
						N/A		Landing Length (in)		0.0	
						N/A		Landing Width (in)		0.0	
						N/A		Landing Slope (%)		0.0	
						N/A		Landing X Slope (%)		0.0	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		0.0	
						N/A		Gutter Lip Ht (in)		2.0	
						N/A		Painted X Walk1?		No	
								X Walk 1 Direction		To S	
						N/A		X Walk 1 Width (in)		N/A	
						N/A		X Walk 1 Slope (%)		0.2	
						N/A		X Walk 1 X Slope (%)		1.1	
						N/A		Ramp inside XWalk1?		N/A	
						N/A		Any Obstructions?		N/A	
								Obstruction Type		Yes	
								Surface Condition? (G/P)		Good	
										Curb Slope (%)	

