cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 46745 Main		Street: CUMBERLAND_COVE_DR		Street:	NORMANS_LANDING	Location:	NE		
ADA ID: 4ED698AFDEF6 Ramp T		ype: PerpDiag	Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	IP I LONG	Possible Solutions:		Compliance Description Data			Compliance Description Data		Data
	A in the	Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.9
		Two New Directional Ramps or		No	Ramp Width (in)	45.5	No	Ramp XSlope (%)	8.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	NORMANS LANDING DR	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
C.	Robuins			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
PROW/ADA: R304.5.1, R304.5.3				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second	And reasons	1004.0.1, 1004.0.0		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A CONTRACTOR OF					X Walk 1 Direction	To W		X Walk 2 Direction	To S
And and a state of the second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CUMBERLAND COVE DR	•			X Walk 1 Slope (%)	6.6		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	6.3
Street 2 Name	NORMANS LANDING DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.8	N/A	Clear Space?	N/A
	None				Road X Slope (%)	6.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.2 N/A		Storm Grate/Utility Hazard?	N/A N/A
		Total Cost: \$	3200.00	11/1	Obstruction Type	N/A		Storm Grate/Utility Type	17/5
			200.00			N/A		Storm Grate/Otimity Type	N/A
						N/A			IN/A