

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28350 Main Street: REA_RD					Cross Street: LINDAHI_LN				Location: NE		
ADA ID: 4F3C21DF6DEB	B Ramp Type: Combination1Diag			Initial I	Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 0		
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data Compliance Description			Data	
		Remove & Replace Cu	Curb Ramp With		N/A	Ramp Length LT (in)	22.0	N/A	Ramp Length RT (in)	39.0	
		Two New Directional R		-	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	50.0	
		Equivalent.			Yes	Ramp Slope LT (%)	0.4	No	Ramp Slope RT (%)	9.2	
					No	Ramp XSlope LT (%)	2.5	No	Ramp XSlope RT (%)	2.7	
		Surveyor Notes:			N/A	Ramp Length (in)	41.0	Yes	Ramp Slope (%)	7.3	
					Yes	Ramp Width (in)	55.0	No	Ramp XSlope (%)	2.8	
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
LINDAHLUN 🗒	10				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
5. 6 5. 5	-0				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Not Found, R304.5.3, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
				N/A	Shared Landing?	N/A					
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	REA RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To NW		X Walk 2 Direction	To S	
Stop Condition-Street 2	LINDHAI LN					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	2.2	
						X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	3.3	
		Total Cost:	\$ 3	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	1.1		Clear Space?	N/A	
						Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A	
		State of all and	- M					N/A	Any Obstruction?	N/A	
STOP				3 Star	f.e.				Obstruction Type		
	Anna Distantial					and the state of the second state of the secon				N/A	
the second							N/A	Storm Grate/Utility Hazard?	N/A		
						A Contraction			Storm Grate/Utility Type		
			2 20					1		N/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 12.9





