

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 45204	Main Street: ALDEMADLE DD				Cross Street: LAW/VERS DD				NW
Intersection ID: 15201	Main Street: ALBEMARLE_RD			Cross Street: LAWYERS_RD				Location:	
ADA ID: 4F4D5D04B446 Ramp Type: Perp			Ini	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1 1	Possible Solutions:		Comp	ance Description Data		Compliance Description		Data
	11 10	Remove & Replace Entire Ra	mp.	N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.0
	and the second		•	No	Ramp Width (in)	45.5	Yes	Ramp XSlope (%)	2.9
	1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and a server			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
19 6 6				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	at o	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	ET C	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	K			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6 1	E			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
E E	<mark>.</mark>			N/A	Shared Landing?	N/A			
ALLIGHT	AL LAND	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
August Santa		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
a a	19100			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	185				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	119.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name LAW	VYERS RD				X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.0	0	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

