

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

16.4

0.1

N/A

No

To S

N/A

4.8

2.2

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 10028610 Main Street: HONOR GUARD AV Cross Street: N/A Location: NE Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 4F5FD9AD9CE7** Ramp Type: PerpDiag Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

127.0

47.0

N/A

No

To W

N/A

0.3

5.3

N/A

0.3

1.6

N/A

N/A



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A

R304.5.1, R304.2.2

PROW/ADA:

HONOR GUARD AV None N/A None N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions?

N/A

No

N/A


Compliance Description

Ramp Length (in)

Ramp Width (in)

Obstruction Type

Flare Type LT



3200.00





Total Cost: