

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

27.0

50.0

5.5

0.3

9.1

6.1

N/A

N/A

Good 28.2

Intersection ID: 7836 Main Street: SNOW WHITE LN **Cross Street: SPRING GARDEN LN** Location: NW **Overall Compliance: No Severity Score:** 42.5 ADA ID: 4F601B096DD9 Ramp Type: Combination1 Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Nο

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Data

30.0

50.0

3.9

1.8

48.5

34.0

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)



StopSign Street 1 Name **SPRING GARDEN LN** Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A No Surveyor Notes: N/A LT RP < 5% N/A PROW/ADA Not Found, R304.5.1, R304.2.2, R304.5.3



Total Cost:



1800.00

N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A N/A **DWS Contrast?** Landing Width (in) N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A N/A Painted X Walk1? No Painted X Walk2? N/A To S X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 0.3 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 3.9 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type

Yes

Surface Condition? (G/P)

Curb Slope (%)

