

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 30148 Main Street: GALESBURG ST Cross Street: OLD PLANK RD Location: **Overall Compliance: No** ADA ID: 4F97535DFAA1 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 



**GALESBURG ST** Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3

Total Cost:



1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Compl	iance	Description	Data
N/A	Ramp Length (in)	43.0	No	Ram	Slope (%)	9.6
Yes	Ramp Width (in)	48.5	No	Ramp	xSlope (%)	3.6
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.8		X Wa	ılk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.2		X Wa	ılk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ice Condition? (G/P)	Good
Nº	A STATE OF THE STA					



