

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: E_7TH_ST Cross Street: N/A Location: E

ADA ID: 4FCC419AD6F5 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name E 7TH ST
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:							
Remove & Replace Entire Ramp.							
·							
Surveyor Notes:							
N/A							
PROW/ADA:							
Not Found, R304.2.2, R304.5.3							
,,,							

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance							
	Comp	liance Description	Data	Comp	liance Description	Data	
	N/A	Ramp Length (in)	76.0	No	Ramp Slope (%)	10.2	
	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.0	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
		X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	N/A	N/A	Clear Space?	N/A	
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Obstruction Type			Storm Grate/Utility Type		
			N/A			N/A	
				Yes	Surface Condition? (G/P)	Good	
100	A SECTION OF	ACTION ACTIONS					





