

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43865 Main Street: SIDNEY_CREST_AV Cross Street: STONE_TRAIL_RD Location: ADA ID: 4FDFDBC1C416 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score:	<u>S</u> 18.75
ADA ID. 41 DI DID TOTTO Rallip Type. 1 etp initial 1 assin all. 1 all over all compliance. No seventy score.	10.75
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance	
Possible Solutions: <u>Compliance Description</u> Data Compliance Description	Data
Remove & Replace Entire Ramp. N/A Ramp Length (in) 49.5 Yes Ramp Slope (%)	7.4
No Ramp Width (in) 33.0 No Ramp XSlope (%)	2.6
N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A
N/A Landing Length (in) N/A DWS Provided?	N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
N/A N/A DWS Length (in)	N/A
N/A Landing X Slope (%) N/A DWS Full Width?	N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A
N/A Shared Landing? N/A	
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A
Not Found, R304.5.1, R304.5.3 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A Painted X Walk2?	N/A
X Walk 1 Direction To W X Walk 2 Direction	N/A
N/A X Walk 1 Width (in) N/A N/A X Walk 2 Width (in)	N/A
Street 1 Name SIDNEY CREST AV X Walk 1 Slope (%) 2.6 X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None X Walk 1 X Slope (%) 1.8 X Walk 2 X Slope (%)	N/A
Street 2 Name N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A N/A Clear Space?	N/A
Road X Slope (%) N/A N/A Clear Space to XWalk (in)	N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard?	N/A
Total Cost: \$ 1850.00 Obstruction Type Storm Grate/Utility Type	
N/A	N/A

Yes Surface Condition? (G/P)

Good

