cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·										
Intersection ID: 15067 Main Street: ALCOTT_ST				Cross Street: WASHBURN_AV					Location:	NW
ADA ID: 509D4C77EF38	Ramp Type: Combination1Diag			Initial Pa	Initial Pass/Fail: Fail Overall Complia			nce: No Severity Score:		0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance										
	Possible Solutions:			Compliance Description			Data Compliance Description			
and the second second		Remove & Replace Curb			N/A	Ramp Length LT (in)	71.0	N/A	Ramp Length RT (in)	68.0
		Two New Directional Ram			Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0
	R Machine Star	Equivalent.			No	Ramp Slope LT (%)	14.9	Yes	Ramp Slope RT (%)	4.7
	TICON				No	Ramp XSlope LT (%)	3.5	No	Ramp XSlope RT (%)	2.8
				N/A	Ramp Length (in)	24.0	No	Ramp Slope (%)	13.4	
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.7	
	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E Constanting	DWS LIP 0.5, ASP LIP 3.0, RT RP <			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
WASHBURN_A	5%			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
in the second					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
All and a second se					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A State The State of State		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
1 to	R304.2.2, R304.5.3, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and the second second	R stands				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	WASHBURN AV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Stop Condition-Street 2	ALCOTT ST					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	10.0		X Walk 2 Slope (%)	1.8
						X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	7.3
		Total Cost:	\$ 32	00.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	8.6		Clear Space?	N/A
						Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
									Obstruction Type	
										N/A
	Constant - Const	de la companya de la	September 4			1 e		N/A	Storm Grate/Utility Hazard?	N/A
									Storm Grate/Utility Type	
1 - Homes			No.S. St		5					N/A
Ye							Yes	Surface Condition? (G/P)	Good	
		The second second		A second	Year			l	Curb Slope (%)	3.7