


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 20834		Main Street: COLONY_CROSSING_DR		Cross Street: COLONY_RD		Location: NE					
ADA ID: 50C5357A5DEF		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 26.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
 <div>Street 1 NameCOLONY CROSSING DR</div> <div>Stop Condition-Street 1None</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A
						Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	0.0
						No	Ramp Slope (%)	12.7	N/A	Grade Break XSlope (%)	0.0
						Yes	Ramp XSlope (%)	3.4			
						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
						N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
						N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
						N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A				
		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A				
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A				
		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A				
		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A				
		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A				
		N/A	Painted X Walk1?	No		Road Slope (%)	3.3				
			X Walk 1 Direction	To SW		Road X Slope (%)	3.8				
			X Walk 1 Width (in)	N/A		Clear Space?	N/A				
			X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A				
			X Walk 1 X Slope (%)	3.8	N/A	Storm Grate/Utility Hazard?	N/A				
		N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type					
		N/A	Any Obstructions?	N/A			N/A				
			Obstruction Type		Yes	Surface Condition? (G/P)	Good				
					N/A	Curb Slope (%)	8.8				
		Total Cost:	\$	1600.00							

