

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47969Main Street: HAWK_SHADOW_LNCross Street: TURNING_HAWK_RDLocation:NEADA ID: 5126EC0DEC0CRamp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

TURNING HAWK RD None HAWK SHADOW LN StopSign

Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes: N/A
PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	51.0	Yes	Ramp	Slope (%)	7.0	
No	Ramp Width (in)	45.5	No	Ramp	XSlope (%)	5.1	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No	
	X Walk 1 Direction	To S		X Wal	k 2 Direction	To NW	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A	
	X Walk 1 Slope (%)	5.7		X Wal	k 2 Slope (%)	0.8	
	X Walk 1 X Slope (%)	1.3		X Wal	k 2 X Slope (%)	4.6	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A	
	Road Slope (%)	4.1	N/A	Clear	Space?	N/A	
	Road X Slope (%)	3.3	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm	Grate/Utility Type		
		N/A				N/A	
			Yes	Surfac	ce Condition? (G/P)	Good	





