

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13085	Main Street: MORRIS_FIELD_DR				Cross Street: CAPITOL_DR				Location: SW		
ADA ID: 517E3AB45D06	Ramp Ty	Ramp Type: Combination2				ail: Fail Overall	nce: No Severity Score: 10		10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description		Data Complia		liance Description	Data	
	- 20 / N	Remove & Rep	lace Entire Rar	np.	N/A	Ramp Length LT (in)	70.0	N/A	Ramp Length RT (in)	N/A	
					Yes	Ramp Width LT (in)	71.0	N/A	Ramp Width RT (in)	N/A	
6. K					Yes	Ramp Slope LT (%)	6.0	N/A	Ramp Slope RT (%)	N/A	
	8				No	Ramp XSlope LT (%)	4.2	N/A	Ramp XSlope RT (%)	N/A	
t. THE	the second				N/A	Ramp Length (in)	71.0	Yes	Ramp Slope (%)	5.5	
THE RU					No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	0.7	
TTors	1 the 2 w	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E.	6. Q	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
and the second					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A State of the second second	C IP N				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ALL PROPERTY OF	CAPITOL DR	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Not Found, R304			04.5.1. R304.5.	3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	A A	,		-	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	Mr. B. C.Y.				N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	MORRIS FIELD DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
and the second second								N/A	Any Obstruction?	N/A	
Designed and the second s			72						Obstruction Type		
										N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 17.5





