


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: TYVOLA_RD	Cross Street: SPEER_BV	Location: E
ADA ID: 518985E8E76E	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	101.0	Yes	Ramp Slope (%)	6.3
			Yes	Ramp Width (in)	69.0	No	Ramp XSlope (%)	4.4
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	9.4	N/A	Flare Slope RT (%)	8.2
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	68.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	69.0	Yes	DWS Contrast?	Yes
			Yes	Landing Slope (%)	0.3	Yes	DWS Length (in)	24.0
			No	Landing X Slope (%)	3.1	Yes	DWS Full Width?	Yes
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3</p>			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.5
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.2
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.5
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
<p>Total Cost: \$ 1850.00</p>				Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good

