## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10014544	Main Str	Cross Street: N/A					Location:	NW	
ADA ID: 51A7AF94417C	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Line and the second sec	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	ith N	I/A	Ramp Length (in)	90.0	Yes	Ramp Slope (%)	6.0
				/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.9
			Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
111 A 14 14 14 14 14 14 14 14 14 14 14 14 14		Surveyor Notes:		I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
The second s		N/A		1/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N	N/A		1/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
EROOKSIDE				1/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				//A	Shared Landing?	N/A		DWS Onset (III)	11/2
TO BE		PROW/ADA:		₩A	0	N/A	N/A	Cuttor Slope (%)	N/A
	AL SAG				Gutter Ponding?			Gutter Slope (%)	
	1 State	R304.5.3	-	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			r	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
		l	N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	51.0
Street 1 Name	BROOKSIDE_LN				X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	4.0
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	7.8
Street 2 Name	ENTRANCE		Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	None				Road Slope (%)	7.7	N/A	Clear Space?	N/A
					Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
			١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

