

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13912 Main Street: E\_STONEWALL\_ST Cross Street: E\_JOHN\_BELK\_RA Location: NW

ADA ID: 51D86A1FA3E6 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name	E STONEWALL ST
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance Description	Data	
N/	A Ramp Length (in)	47.5	Yes	Ramp Slope (%)	5.8	
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.2	
N/A	A Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/	A Shared Landing?	N/A				
N/	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	A Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/	A Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/	A X Walk 1 Width (in)	117.0	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A	
N/	A Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/	A Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
-						





