

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13240 Main Street: OLD_STEELE_CREEK_RD **Cross Street: WILLOW ST** Location: SW ADA ID: 51E3FF0E9EC1 Ramp Type: ParaDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 **OLD STEELE CREEK RD** None

WILLOW ST

StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: RT RP < 5%

PROW/ADA:

Total Cost:

R304.3.2, R304.5.3





3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Comp	liance Description	Data
N/A	Ramp Length LT (in)	64.0	N/A	Ramp Length RT (in)	48.0
Yes	Ramp Width LT (in)	107.0	Yes	Ramp Width RT (in)	107.0
No	Ramp Slope LT (%)	11.1	Yes	Ramp Slope RT (%)	0.2
No	Ramp XSlope LT (%)	3.2	No	Ramp XSlope RT (%)	3.0
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	То Е		X Walk 2 Direction	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.7		X Walk 2 Slope (%)	2.3
	X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	4.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	5.2	N/A	Clear Space?	N/A
	Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	7.1