


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17190	Main Street: MURRAYHILL_RD	Cross Street: SCALEYBARK_RD	Location: NW
ADA ID: 51E44005FF34	Ramp Type: Combination2	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	N/A
			N/A	Ramp Width LT (in)	N/A
			N/A	Ramp Slope LT (%)	N/A
			N/A	Ramp XSlope LT (%)	N/A
			N/A	Ramp Length (in)	24.0
			Yes	Ramp Width (in)	60.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>Surveyor Notes:</p> <p>N/A</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A
<p>PROW/ADA:</p> <p>R304.3.2, R304.5.3</p>			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NE
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	2.9
				X Walk 1 X Slope (%)	0.9
			N/A	Ramp inside XWalk1?	N/A
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
<p>Total Cost:</p> <p>\$ 1600.00</p>			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	3.6

