


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 16365	Main Street: QUEENS_RD	Cross Street: SHERWOOD_AV	Location: SE
ADA ID: 51E9AD5157C2	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 12.5			

	Possible Solutions:				
	Remove & Replace Entire Ramp.				
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2</p>			Compliance	Description	Data
			Compliance	Description	Data
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>			N/A	Ramp Length (in)	72.0
			Yes	Ramp Width (in)	48.0
			No	Ramp Slope (%)	8.4
			Yes	Ramp XSlope (%)	1.1
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	0.0
			N/A	Landing Width (in)	0.0
			N/A	Landing Slope (%)	0.0
			N/A	Landing X Slope (%)	0.0
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	0.0
			N/A	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	5.0
				X Walk 1 X Slope (%)	4.7
			N/A	Ramp inside XWalk1?	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	9.6
Total Cost:		\$	1600.00		

