

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54415	Main Street: GLANMIRE_DR			Cross Street: ARDREY_KELL_RD				Location:	SW	
ADA ID: 51FF4D3A4DC1	1 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
and stand in the		Remove & Replace Entire Ram	<b>D</b> .	N/A	Ramp Length (in)	79.0	N/A	Grade Break?	N/A	
A HA SHIELD				Yes	Ramp Width (in)	68.0	N/A	Grade Break Slope (%)	0.0	
				No	Ramp Slope (%)	11.4	N/A	Grade Break XSlope (%)	0.0	
b b	ELL-RD			Yes	Ramp XSlope (%)	0.5				
ATERIAL	aus	1		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Alithur .	6.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
6-1-	a the second second	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Carrier Carlo Carlos	A	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	R.			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
· 小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小小				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
and the second second	E E	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	123	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	800112			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
THE SHALL IN				N/A	Painted X Walk1?	No		Road Slope (%)	1.8	
Street 1 Name	GLANMIRE DR	-			X Walk 1 Direction	To E		Road X Slope (%)	2.0	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.0	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	1.1	

